1. Also eligible on Model PA-28-151 When Modified Per STC SA2969SW (160 H.P. Engine Conversion). (See Continuation Sheet, Page 2, a part of this STC.)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: 6-26-97

Date of issuance: 6-30-97

Date reissued:

Date amended:

By direction of the Administrator



William J. Thomas

DAS Staff Coordinator, DAS 5 SW

(Title)

### **Reiff Preheat Systems**

Long engine life starts with Reiff.

S14 W31825 High Meadow Ln. Delafield, WI 53018 Phone/Fax: 262-968-2342 E-mail: Reiff@execpc.com

www.execpc.com/reiff

# HOTPADD OIL SUMP HEATER INSTALLATION INSTRUCTIONS

Failure to follow these instructions may result in product failure and warranty invalidation. If any of these instructions are unclear, please call for clarification before beginning.

- 1) CAUTION: <u>DO NOT CUT THE PAD</u> OR PLUG IT IN BEFORE IT IS INSTALLED. Doing so may ruin it, but you should test it before installation by plugging it in for a few seconds until it begins to feel warm.
- 2) The pad should be installed on a smooth, flat surface on the bottom or side of the oil sump below the oil level, with suitable clearance from moving parts such as throttle linkage. It is CRITICAL to have good pad-tometal contact over the entire area of the pad. Any part of the pad that is not against metal will cause a hot spot on that part of the pad and its life expectancy will be reduced. Do not install over a dented or concave surface (dished in), bolts, cast letters, weld seams, ridges, or any voids more than normal surface roughness. Any raised numbers in the casting must be ground down flush with the sump surface. Voids should NOT simply be filled in with adhesive. If necessary, the pad is able to bend around gentle contours but should not be mounted over sharp bends. INSTRUCTIONS FOR SPECIFIC ENGINES: Large Continentals with stamped oil sumps, the side is the preferred location due to being flatter than the bottom. Small Continentals with kidney tanks, mount the pad horizontally on the front or rear. The thermostat tab will not lay flat so fill in the raised edge with adhesive. Lycoming O-320/360, put it on the right side of the bottom. Lycoming O-320-H, install vertically on the front side. Lycoming IO-360-A, Model 213 wraps around the left side of the oil sump, opposite the engine data plate. Lycoming IO-360-C, Model 56 installs horizontally on the bottom surface of the shelf above the front right intake tube, with the cord facing towards the center. Lycoming IO-540, install both Model 540 pads above the intake tubes with the larger pad (with the thermostat tab) on the left rear of the sump with cord facing aft, and the smaller pad on the right rear with cord aft. Lycoming 0-540 on Cessna 182RG, Model 331-A installs vertically on the right side. Lycoming 541, Model 57 installs on the flat section that slopes up and forward.
- 3) The adhesive will need to be kept at 75° F or higher for 24 hrs. to properly cure. Use a heat lamp or other means to do this if necessary.
- 4) Proper surface preparation is CRITICAL to the quality of the adhesive bond and the life of the heater pad. Remove the paint from the oil sump. This is easily done by tracing the outline of the pad with a felt tip pen, then using a wire brush in a Dremel tool, or paint remover, to remove the paint inside the drawn outline. Do not polish the surface a rough surface gives the best adhesion. The surface must be clean and dry. Clean the installation area using Permatex 4MA Gasket Remover or equivalent, or a residue-free solvent such as isopropyl alcohol, heptane, lacquer thinner, acetone, or M.E.K. (no gasoline, kerosene, etc.).

#### United States Of America Bepartment of Transportation - Federal Abiation Administration

## Supplemental Type Certificate

Number SA01071LA

This Berliftende issued to

Met-Co-Aire 14656½ Firestone Blvd La Mirada, California 90638

certifies that the change in the type design for the following product with the limitations and conditions therfor as specified hereon meets the airmorthiness requirements of Part 23\* of the Foderal Aniation Regulations.

Prininal Product Type Certificate Number:

\*See attached FAA Approved Model List (AML) No. SA01071LA for list of approved airplane models and applicable airworthiness regulations.

Model:

Description of Typo Design Change: Installation replacement tail cone fairing assembly in accordance with FAA approved Met-CO-Aire Controlled Drawing List, MA1-1-03, dated September 10, 2000, or later FAA approved revision.

Bimilations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in offect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aniation Administration.

Date of application: June 29, 2000

Dala of issunce : October 6, 2000 Dula reissued :

Date umended:



direction of the Administrator

(Signature) Manager, Airframe Branch Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both

This certificate may be transferred in accordance with

## Brantford Flying Club Major Repair or Modification Report

| . Aircraft   | Make  | Model                                 |
|--|---|---------------------------------------|
|  | PIPER   | PA 28-181                             |
|  | Serial No. 7690334                                |                                       |
|  |   | Registration Marks                    |
| Owner  | Name  | C-GSLM                                |
|  | BPL Aviation Inc.                                 | O-GOLINI                              |
| Type of work   |   |                                       |
|  | ☐ Modification                                    | ☑ ( Repair                            |
|  |   |                                       |
| Name and address   | of person or organization who accomplished the re | epair or modification                 |
|  |   |                                       |
|  |   |                                       |
| Brantfor   | rd Flying Club, P.O. Box 903, Brantfo             | ord, On. N3T 5L7                      |
| D.G.M.   |   |                                       |
|  |   |                                       |
|  |   |                                       |
| escription of work   | accomplished                                      |                                       |
| la stall   | now midder ekin D.N. 62206 902 I.A.               | W Dinor Maintenance Manual            |
|  | new rudder skin P.N. 63396-802 I.A                |                                       |
| The state of the s | r 51-10-00 and AC 43.13-1B, 4-57 (                | Riveting), using original rivet sizes |
| and spa  | acing thruout.                                    |                                       |
| Pudde  | r prepade primed and painted to me                | atab original                         |
| -Nuude   | r prepped, primed and painted to ma               |                                       |
| -Contro  | I surface balance checked                         | 95/8 IN/45 (13.5 LIM)                 |
|  |   | 18.1                                  |
|  |   |                                       |
|  |   |                                       |
|  |   |                                       |
|  |   |                                       |
|  |   |                                       |
|  |   |                                       |
|  |   |                                       |
|  |   |                                       |
| 1 1 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3  |   |                                       |

Signature of person submitting report \_\_\_\_

Muy ( RCT )

### MAJOR REPAIR AND MAJOR MODIFICATION REPORT

| 1. Aircraft  | Make  |                    |
|--|---|--------------------|
|  | Piper   | Model              |
|  | Serial No.  | PA28-              |
|  | 28-7690334  | 181                |
| 2. Owner   | Name  |                    |
|  | BPL Aviation  | Registration marks |
|  |   | C-GSLM             |
|  |   |                    |
| 3. Type of work  | k   |                    |
|  | X Modification Repair   |                    |
| 4. Name and ad   | ddress of person or organization who accomplished the repair or m | odification        |
| Brantford F  | lying Club AMO 153-92   |                    |
| P.O. Box 90  | Phone 1-519-753-2521  |                    |
| Brantford, C   | On N3T 5S1 Fax 1-519-753-3617                                     |                    |
| 6 David  |   |                    |
| 5. Description   | of work accomplished  |                    |
| Installed Insigh   | nt G2 Graphic Engine Monitor in accordance with installation man  | mal 6100 001 D     |
|  |   |                    |
| Installed Insigh   | nt fuel flow signal adapter 610C-025 in accordance with drawing h | No. 101116.        |
| Aircraft retains   | s Shadin fuel flow as the primary system.                         | *                  |
| Weight & Bala  | ince and Equipment List amended.                                  |                    |
| Installed AFM  | supplement Document No. 610C-FMS                                  |                    |
|  |   |                    |
| END  | ,   |                    |
|  |   |                    |
|  |   |                    |
|  |   |                    |
| 8.8  |   |                    |
|  |   |                    |
|  |   |                    |
| 8 .  |   |                    |
|  |   |                    |
| ATE TO THE TOTAL T |   |                    |
| 3,   |   |                    |
|  |   |                    |
|  |   |                    |
|  |   |                    |
| DO FORM  | MEXT??  □□ FORMEXT??  □□ FORMEXT??                                | ECOMEYT201         |
| EVT  | TO LOIGHT TO LOIGHT TO LOIGHT TO                                  | DO FORMEXT??       |

**EXT** 

16 AUG 2013

Department of Transportation—Bederal Aviation Administration

### -MPORTANT DOCUMENTAL Type Certificate

KEEP WITH AIRCRAFT RECORDS

Number SA01643SE

B.A.S. Inc. Ser. # 242

ATTENTION: CHECK REEL OPERATION BEFORE EACH FLIGHT

Lift Buckle

Latch For Removal !



Incorrect: Buckle Too High



Utility Float Plane Buckle



Incorrect: Buckle Must Be Centered



Pull Belt Ends To Tighten



Pull Strap Ends To Tighten 190/195 & Luscombe

he limitations and conditions 23 of the Federal Aviation

Approved Model List (AML) ist of approved airplane models thiness regulations.

er harness with inertia reel in r FAA-approved revision.

ies only to the model aircraft other aircraft of this model on is determined that the ved modifications, including iness of that aircraft. A copy just be maintained as part of

the product, the holder shall

rmain in effect until by the Administrator of the



Standard Buckle



Pull Tabs to Loosen 190/195 & Luscombe

|                                    | 'Mill  |
|------------------------------------|--------|
|                                    | ature) |
| Take to Loosen 190/195 & Lus combe | le)    |

stor

ling 3 years, or both.

ed in accordance with FAR 21.47.

| T 10 malement          | Report 1302                              |
|------------------------|--|
| ners Manual Supplement | Page 1 of 1                              |
|                        | 7.794                                    |
| BAS Incorporated       |  |
|                        | ners Manual Supplement  BAS Incorporated |

### Department of Transportation -- Federal Abiation Administration

| Supplementa   | l Type Certific  | ate  |
|---|--|--|
| This certificate issued to Plane Dynamix, LLC 3650 Rogers Road, Suite Wake Forest, NC 27587  This STC is Valid Only as Registered Plane Dynamix, LLC 407-917-2 certifies that the change in the type design for the therefore as specified hereon meets the aircrafting (See Type Certificate Data Sheet Number 2A13) | l Type Certific<br>GPS 508<br>wher sattoch   | 8 10 m   |
| This certificate issued to Plane Dynamix, LLC 3650 Rogers Road, Suite Wake Forest, NC 27587   | 231 S CX   |  |
| Plane Dynamix, LLC 407-917-2 certifies that the change in the type design for the   | Jollowing product with the Soldier   | ns and conditions<br>A Air Regulations   |
| (See Type Certificate Data Sheet Number 2A13  | for the complete certification basis.)   |  |
| Original Product Type Certificate Number :  | 2A13   | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>7<br>8<br>8<br>8<br>8<br>8<br>8<br>8<br>8<br>8 |
| . Make :  | Piper Aircraft Corporation   | Ps   |
| . Hodel:  | PA-28-140, PA-28-150, PA-28-151, PA-28<br>PA-28-161, PA-28-180, PA-28-181, PA-28<br>PA-28-236, PA-28S-160, PA-28S-180,<br>PA-28R-180, PA-28R-200, PA-28R-201,<br>PA-28R-201T, PA-28-201T   | -160,  |
| Lescription of Type Lesign Change:<br>Installation of 3M Scotch #8672 one inch wide polyurethan<br>to the installation instructions titled "Aileron Gap Seal" and<br>later FAA approved revisions.  | ne tape as gap seals for the ailerons and the sta<br>d "Stabilator-Trim Tab Gap Seal", no revision   | abilator trim tabs according<br>is, dated August 18, 1995, or                                    |
| Limitations and Conditions:  1) The installer must determine whether this design changes the Never Exceed Speed (VNE) for the modification The Airplane Flight Manual Supplement, dated September 1.  | nge is compatible with previously approved m<br>is limited to 186 knots (214 mph) Indicated A<br>ember 24, 1996 or later FAA approved revision   | iodifications.<br>Airspeed (IAS).<br>ins, is required with this                                  |
| <ul> <li>modification.</li> <li>If the airplane is certified with a VNE lower than 214</li> <li>If the holder agrees to permit another person to use the written evidence of that permission.</li> </ul>  | 4 mph, then this lower VNE remains in effect. his certificate to alter the product, the holder n   | nust give the other person   |
| This certificate and the supporting data, which surrendered, suspended, revoked or a termination  | is the basis for approval, shall remail<br>a date is otherwise established by the .  | n in effect until<br>Administrator of the  |
| Federal . Aviation . Administration.  |  |  |
| Late of application . October 21. 1994  | Late reissued : August 26, 2015  |  |
| Sale of issuance : December 12, 1995  | Late amended : September 24, 1996<br>By direction of the Adminish  |  |
|   | Signature)   |  |
| Mala Ala  | The second secon |  |



Karol Mordasiewicz Manager, Airframe and Administrative Branch Chicago Aircraft Certification Office

(Title)