

- RH brake calliper leaking fluid. RH brake caliper re & re, cleaned. Replaced O'ring seal with new P/N MS28775-224.
- RH/LH brakes serviced with MIL-PRF-5606 fluid.

"The described maintenance has been performed in accordance with the applicable airworthiness requirements."

Sign:

A. [Signature]

#836665

Date:

May 5/2026

8084.2

Date: Aug 11, 2026

Annual Inspection C-172N C-GJNN

Serial # 172-71973 TTAF:8084.2

Engine: TSMOH 1864.3

Prop: TTSN 14.7

- Annual Inspection carried out IAW CAR 6235 Appendix B&C
- Sensenich Propeller inspected. Spinner re&re
- Compression Check Carried Out: 1. 74/80 2. 70/80 3. 78/80 4. 78/80
- Engine oil drained and sump re-filled with Phillips 20W50 XC oil
- Oil Filter removed and inspected. Nothing significant found. New filter installed.
- Fuel Strainer bowl re&re for inspection and cleaning.
- Cleaned and checked gap on Spark Plugs.
- Tires inflated to Specs.
- ELT Checked and tested
- Aircraft lubricated per Cessna Service Manual
- Fire Extinguisher inspected, weight checked OK and gauge in Green Arc.
- First Aid Kit checked, serviceable
- Tachometer checked, Within Limits.
- Magnetic Compass Swing carried out. *No Change*
- AD CF90-0R2 Muffler Inspection carried out, serviceable.
- AD 2011-10-09 Seat rail and roller inspection carried out, serviceable.
- AD 2026-04-11 ATA 72 Engine Connecting Rod Bushing Inspection carried out, serviceable.
- Ground Run carried out. Engine parameters normal, no abnormalities noted.

The Described maintenance has been performed in accordance with the applicable airworthiness requirements.

Sign:

[Signature]

M115319

Date:

Aug 11/2026

PAGE
TOTALS

CARRY FORWARD to Top of Next Page